SDMS US EPA Region V

Imagery Insert Form

Document ID:



Some images in this document may be illegible or unavailable in SDMS. Please see reason(s) indicated below:

Illegible due to bad source documents. Image(s) in SDMS is equivalent to hard copy.
Specify Type of Document(s) / Comments:
IncludesX COLOR orX RESOLUTION variations.
Unless otherwise noted, these pages are available in monochrome. The source document page(s) is more legible timages
Specify Type of Document(s) / Comments:
SITE PHOTOGRAPHS
Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are
in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document.
Specify Type of Document(s) / Comments:
Unscannable Material:
Oversized or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS.
Specify Type of Document(s) / Comments:
Document is available at the EPA Region 5 Records Center.

Rev. 07/10/02

SAUGET AREA 2, SAUGET, ILLINOIS

REMEDIAL INVESTIGATION/ FEASIBILITY STUDY REPORT VOLUME 3 Appendix A

Prepared for

Sauget Area 2 Sites Group c/o Gary Uphoff Environmental Management Services 5934 Nicklaus Drive Fort Collins, CO 80528



January 30, 2004

URS

URS Corporation 1001 Highland Plaza Drive West, Suite 300 St. Louis, MO 63110 (314) 429-0100 **Project #21560888.07001** Sauget Area 2 Sites Group

Revision No.: 1 Date: 01/30/04

APPENDIXA

Photographs

Table of Contents for Photographs

- Α Soil Gas
- **Boundary Trenches** В
- **Anomaly Trenches** C
- Waste Borings D
- Leachate Wells E
- F Well Sampling
- Bedrock Wells G
- Well Development Н
- Piezometers I
- J Off-Site Soil Borings
- Air Sampling K
- Seep Survey L
- Slug Tests M
- N Site P
- Southern Q Ponds O



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **A.1**

Date: 6-24-02

Description:

SG-R-33

Direction Photo Taken:

West



Photo No.

Date:

A.2

6-24-02

Description:

SG-R-33

Direction Photo

Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group


Sauget, Illinois

21560888

Photo No.
A.3

Date: 6-24-02

Description: SG-P-38



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.1**

Date: 6/17/02

Description:

Boundary Trench-O-1 Before

Direction Photo


Taken: East



Photo No. **B.2**

Date: 6/17/02

Description:



PHOTOGRAPHIC LOG

Client Name:Site Location:Project No.Sauget Area 2 GroupSauget, Illinois21560888

Photo No. Date: 6/17/02

Description:

Boundary Trench-O-1



Photo No.
B.4 6/17/02

Description:
BoundaryTrench-O-1

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. **B.5**

Date: 6/17/02

Description:

Boundary Trench-O-2 Before




Photo No. B.6 **Date:** 6/17/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Date: 6/17/02 Sauget, Illinois

21560888

B.7 Description:

Photo No.


Boundary Trench-O-2



Photo No. **B.8**

Date: 6/17/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.9**

Date: 6/17/02

Description:

BT-O-2 After

Direction Photo

Taken: Southwest



Photo No. **B.10**

Date: 6/17/02

Description: BT-O-2 After

Direction Photo Taken:

South



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.11**

Date: 6/17/02

Description:

Boundary Trench-O-3

Before

Direction Photo

Taken: East



Photo No. **B.12**

Date: 6/17/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.13**

Date: 6/17/02

Description:Boundary Trench-O-3




Photo No. **B.14**

Date: 6/17/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 6/17/02

Description:

Boundary Trench-O-3



Photo No. B.16 **Date:** 6/17/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illniois

Project No.

21560888

Photo No. Date: 6/17/02

Description:

Boundary Trench-O-3




Photo No. B.18 **Date:** 6/17/02

Description:

Boundary Trench-O-3

Direction Photo Taken:

South



URS PHOTOGRAPHIC LOG Client Name: Site Location: Project No. Sauget Area 2 Group Sauget, Illinois 21560888 Photo No. Date: **B.19** 6/17/02 Description: Boundary Trench-O-3 After **Direction Photo** Taken: South

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.20**

Date: 6/14/02

Description:

Boundary Trench-O-4 Before

Direction Photo Taken:

West




Photo No. **B.21**

Date: 6/14/02

Description:

Boundary Trench-O-4 Before

Direction Photo Taken:

North



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.22

Date: 6/14/02

Description:

Boundary Trench-O-4

0-4

Direction Photo

Taken:

North



Photo No. B.23

Date: 6/14/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. B.24

Date: 6/14/02

Description:

Boundary Trench-O-4



Photo No. B.25 **Date:** 6/14/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.26

Date: 6/14/02

Description:

Boundary Trench-O-4



Photo No. B.27 Date: 6/14/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.28

Date: 6/14/02

Description:

Boundary Trench-O-4



Photo No. B.29

Date: 6/14/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.30**

Date: 6/14/02

Description:

Boundary Trench-O-4



Photo No.

B.31

Date: 6/14/02

Description:Boundary Trench-O-4



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.32

Date: 6/14/02

Description:

Boundary Trench-O-4

After

Direction Photo

Taken: North



PHOTOGRAPHIC LOG

Client Name: Site Location: Project No.

Sauget Area 2 Group Sauget, Illinois 21560888

Photo No. Date: 6/12/02

Description:Boundary Trench-P-1
Before

Direction Photo Taken: North




Photo No. Date: 6/12/02

Description:Boundary Trench-P-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. **B.35**

Date: 6/12/02

Description:Boundary Trench-P-1




Photo No. **B.36**

Date: 6/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. **B.37**

Date: 6/12/02

Description:Boundary Trench-P-1



Photo No. **B.38**

Date: 6/12/02

Description:Boundary Trench-P-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No. **B.39**

Date: 6/12/02

Description:

Boundary Trench-P-1





Photo No. **B.40**

Date: 6/12/02

Description:Boundary Trench-P-1 After

Direction Photo Taken:

North



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.41

Date: 6/12/02

Description:

Boundary Trench-P-2





Photo No. B.42

Date: 6/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.43 Date: 6/12/02

Description:

Boundary Trench-P-2



Photo No. B.44 **Date:** 6/12/02

Description:

Boundary Trench-P-2 After

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.45**

Date: 6/12/02

Description:

Boundary Trench-P-2

Before

Direction Photo

Taken:

East




Photo No. **B.46**

Date: 6/12/02

Description:

Boundary Trench-P-2

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.47

Date: 6/12/02

Description:

Boundary Trench-P-2




Photo No.

B.48

Date: 6/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.49

Date: 6/12/02


Description:

Boundary Trench-P-3



Photo No. B.50 **Date:** 6/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.51

Date: 6/12/02

Description:

Boundary Trench-P-3




Photo No. B.52


Date: 6/12/02

Description:

Boundary Trench-P-3 After

Direction Photo Taken:

South



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.53**

Date: 6/12/02

Description:

Boundary Trench-P-4

Before

Direction Photo

Taken: North



Photo No. **B.54**

Date: 6/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.55**

Date: 6/12/02


Description:Boundary Trench-P-4



Photo No. **B.56**

Date: 6/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.57

Date: 6/12/02

Description:

Boundary Trench-P-4




Photo No.

B.58

Date: 6/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.59

Date: 6/12/02

Description:

Boundary Trench-P-4



Photo No.

B.60

Date: 6/12/02

Description: BT-P-4 After

Direction Photo Taken:

North



URS PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No. 21560888

Sauget Area 2 Group

Sauget, Illinois

Photo No. **B.61**

Date: 6/12/02

Description:

Boundary Trench-P-4 After

Direction Photo Taken:

Southeast



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.62**

Date: 6/4/02

Description:

Boundary Trench-Q-1 Before – 1st Attempt

Direction Photo Taken:

South




Photo No.

B.63

Date: 6/4/02


Description:

Boundary Trench-Q-1 Before

Direction Photo

Taken:

South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.64**

Date: 6/4/02

Description:

Boundary Trench-Q-1 Before

Direction Photo

Taken: Southeast





Photo No. B.65 **Date:** 6/4/02

Description:

Boundary Trench-Q-1

Direction Photo Taken:
Northeast



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.66**

Date: 6/4/02

Description:


Boundary Trench-Q-1



Photo No. **B.67**

Date: 6/4/02

Description:Boundary Trench-Q-1



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illniois

Project No.

21560888

Photo No. B.68

Date: 6/4/02

Description:

Boundary Trench-Q-1



Photo No. B.69 **Date:** 6/4/02

Description:

Boundary Trench-Q-1

Direction Photo

Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.70**

Date: 6/4/02

Description:Boundary Trench-Q-1





Photo No. **B.71**

Date: 6/4/02

Description:Boundary Trench-Q-1



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location: Sauget, Illinois

Project No. 21560888

Photo No.

B.72

Date:

6/4/02

Description:Boundary Trench-Q-1





Photo No. **B.73**

Date: 6/4/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.74

Date: 6/4/02


Description:

Boundary Trench-Q-1



Photo No. B.75 Date: 6/4/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.76**

Date: 6/4/02


Description:Boundary Trench-Q-1



Photo No. **B.77**

Date: 6/4/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.78

Date: 6/4/02

Description:

Boundary Trench-Q-1

• • •

Direction Photo

Taken: South



Photo No. B.79

Date: 6/4/02


Description:

Boundary Trench-Q-1

Direction Photo

Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Sauget, Illinois

21560888

Photo No. **B.80**

Date: 6/4/02

Description:

Boundary Trench-Q-1





Photo No. **B.81**

Date: 6/4/02

Description:Boundary Trench-Q-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. B.82

Date: 6/4/02

Description:

Boundary Trench-Q-1 After

Direction Photo

Taken: East





Photo No. B.83 **Date:** 6/4/02

Description:

Boundary Trench-Q-1 After

Direction Photo Taken:
Southeast



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. B.84

Date: 6/4/02

Description:

Boundary Trench-Q-1 After

Direction Photo Taken:

Southeast




Photo No. B.85

Date: 6/4/02

Description:

Boundary Trench-Q-1 After

Direction Photo Taken:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.86**


Date: 6/4/02

Description:
Boundary Trench-Q-1
After

Direction Photo

Taken:

South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.87

Date: 6/10/02

Description:

Boundary Trench-Q-1 Before – Offset location, 2nd Attempt

Direction Photo

Taken: East




Photo No.

B.88

Date: 6/10/02


Description:

Boundary Trench-Q-1 Before

Direction Photo

Taken:

Southeast



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

Photo No. **B.89**

Date: 6/10/02

Description:

Boundary Trench-Q-1

21560888

Direction Photo Taken:

Southwest




Photo No.

B.90

Date: 6/10/02

Description:Boundary Trench-Q-1

Direction Photo

Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.91**

Date: 6/10/02

Description:


Boundary Trench-Q-1



Photo No. **B.92**

Date: 6/10/02

Description:Boundary Trench-Q-1



Client Name: Sauget Area 2 Group Photo No. B.93 Description: Boundary Trench-Q-1

Photo No. B.94

Date: 6/10/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.95

Date: 6/10/02

Description:

Boundary Trench-Q-1



Photo No. B.96 **Date:** 6/10/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.97

Date: 6/10/02

Description:

Boundary Trench-Q-1





Photo No. B.98 Date: 6/10/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.99**

Date: 6/10/02

Description:

Boundary Trench-Q-1





Photo No. **B.100**

Date: 6/10/02

Description:Boundary Trench-Q-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.101**

Date: 6/10/02

Description:Boundary Trench-Q-1



Photo No. B.102

Date: 6/10/02

Description:Boundary Trench-Q-1



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.103**

Date: 6/10/02

Description:Boundary Trench-Q-1



Photo No. **B.104**

Date: 6/10/02

Description:Boundary Trench-Q-1

Direction Photo Taken: Northwest




URS PHOTOGRAPHIC LOG Project No. Client Name: Site Location: Sauget Area 2 Group Sauget, Illinois 21560888 Photo No. Date: **B.105** 6/10/02 Description: Boundary Trench-Q-1 After **Direction Photo** Taken: East

Photo No. B.106 **Date:** 6/10/02

Description:

Boundary Trench-Q-1 After

Direction Photo Taken: South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Photo No. Date

Date: 6/5/02

B.107

Description:
Boundary Trench-Q-3
Before

Direction Photo

Taken: South





Photo No. B.108 **Date:** 6/5/02

Description:

Boundary Trench-Q-3 Before

Direction Photo Taken:

North



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No. 21560888

Photo No. **B.109**

Date: 6/5/02

Description:
Boundary Trench-Q-3
Before

Direction Photo Taken:

East




Photo No. **B.110**

Date: 6/5/02

Description:

Boundary Trench-Q-3

Direction Photo Taken:

South



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.111**

Date: 6/5/02

Description:Boundary Trench-Q-3




Photo No. **B.112**

Date: 6/5/02

Description:Boundary Trench-Q-3

Direction Photo Taken:

Southwest



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.113

Date: 6/5/02

Description:Boundary Trench-Q-3



Photo No. **B.114**

Date: 6/5/02

Description:



PHOTOGRAPHIC LOG

Client Name: Sauget Area 2 Group Site Location: Sauget, Illinois Project No. 21560888

Photo No. B.115

Date: 6/5/02

Description:

Boundary Trench-Q-3




Photo No. B.116 **Date:** 6/5/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.117

Date: 6/5/02

Description:

Boundary Trench-Q-3





Photo No. **B.118**

Date: 6/5/02

Description:Boundary Trench-Q-3
After

Direction Photo Taken:

North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.119

Date: 6/5/02

Description:

Boundary Trench-Q-3

After

Direction Photo

Taken: East





Photo No. B.120

Date: 6/5/02

Description:

Boundary Trench-Q-3 After

Direction Photo Taken: South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No. 21560888

Photo No. B.121

Date: 6/21/02

Description:

Boundary Trench-Q-5 Before

Direction Photo

Taken: South




Photo No. B.122 **Date:** 6/21/02


Description:

Boundary Trench-Q-5 Before

Direction Photo

Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.123**

Date: 6/21/02

Description:Boundary Trench-Q-5 Before

Direction Photo

Taken: West




Photo No. **B.124**

Date: 6/21/02

Description:

BT-Q-5



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.125

Date: 6/21/02

Description:

Boundary Trench-Q-5




Photo No. B.126

Date: 6/21/02

Description:



URS **PHOTOGRAPHIC LOG**

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.127**

Date: 6/21/02

Description:Boundary Trench-Q-5





Photo No. **B.128**

Date: 6/21/02

Description:

Electrical Conduit



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.129

Date:

6/21/02

Description:

Boundary Trench-Q-5 After

Direction Photo

Taken: West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.130**

Date: 6/6/02

Description:

Boundary Trench-Q-6 Before

Direction Photo Taken:

East




Photo No. **B.131**

Date: 6/6/02

Description:Boundary Trench-Q-6 Before

Direction Photo

Taken: West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 6/6/02

Description:

Boundary Trench-Q-6



Photo No. B.133

Date: 6/6/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.134**

Date: 6/6/02

Description:Boundary Trench-Q-6




Photo No. B.135

Date: 6/6/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.136

Date: 6/6/02

Description:

Boundary Trench-Q-6

-0

Direction Photo Taken:

East




Photo No. B.137 **Date:** 6/6/02

Description:

Boundary Trench-Q-6 After

Direction Photo

Taken: West



URS Client Name: Sauget Area 2 Group Sauget, Illinois PHOTOGRAPHIC LOG Project No. 21560888


Photo No. Date: 6/6/02

Description:

Boundary Trench-Q-6 After

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.139**

Date: 6/10/02

Description:

Boundary Trench-Q-7 Before

Direction Photo

Taken: South




Photo No. **B.140**

Date: 6/10/02

Description:Boundary Trench-Q-7 Before

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.141**

Date: 6/10/02

Description:Boundary Trench-Q-7



Photo No. **B.142**

Date: 6/10/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.143

Date: 6/10/02

Description:

Boundary Trench-Q-7



Photo No. B.144 **Date:** 6/10/02

Description:

Boundary Trench-Q-7 After

Direction Photo

Taken: East



URS **PHOTOGRAPHIC LOG** Project No. **Client Name:** Site Location: 21560888 Sauget Area 2 Group Sauget, Illinois Photo No. Date: 6/10/02 **B.145** Description: BT-Q-7 After **Direction Photo** Taken: Southeast

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.146**

Date: 8/12/02

Description: Boundary Trench-Q-8 Before

Direction Photo Taken:

West




Photo No. **B.147**

Date: 8/12/02

Description:



URS **PHOTOGRAPHIC LOG**

Project No. Client Name: Site Location: Sauget Area 2 Group 21560888 Sauget, Illinois

Photo No. Date: **B.148** 8/12/02 **Description:**Boundary Trench-Q-8




Photo No. **B.149**

Date: 8/12/02

Description: BT-Q-8



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.150**

Date: 8/12/02

Description:Boundary Trench-Q-8

Direction Photo Taken:

East



Photo No. **B.151**

Date: 8/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.152**

Date: 8/12/02

Description:

Boundary Trench-Q-8




Photo No. **B.153**

Date: 8/12/02


Description:

Boundary Trench-Q-8 After

Direction Photo

Taken:

Northwest



PHOTOGRAPHIC LOG

Client Name:Site Location:Project No.Sauget Area 2 GroupSauget, Illinois21560888

Photo No. Date: 8/12/02

Description:

Boundary Trench-Q-8 After

Direction Photo Taken:
Northwest



URS PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.155**

Date: 8/12/02

Description:Boundary Trench-Q-9 Before

Direction Photo Taken:

North




Photo No. **B.156**

Date: 8/12/02

Description:Boundary Trench-Q-9 Before

Direction Photo

Taken: North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.157

Date: 8/12/02

Description:


Boundary Trench-Q-9



Photo No. B.158 Date: 8/12/02

Description:

BT-Q-9



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.159

Date: 8/12/02

Description:

Boundary Trench-Q-9




Photo No. B.160 **Date:** 8/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.161

Date: 8/12/02

Description:

Boundary Trench-Q-9




Photo No. B.162 **Date:** 8/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.163**

Date: 8/12/02

Description:

Boundary Trench-Q-9

Direction Photo

Taken:

East



Photo No. **B.164**

Date: 8/12/02

Description:Boundary Trench-Q-9



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.165**

Date: 8/12/02

Description:

Boundary Trench-Q-9




Photo No. **B.166**

Date: 8/12/02

Description:Boundary Trench-Q-9



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.167

Date: 8/12/02

Description:

Boundary Trench-Q-9



Photo No. B.168 Date: 8/12/02


Description:

Boundary Trench-Q-9 After

Direction Photo

Taken:

North



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.169

Date: 8/12/02

Description:

Boundary Trench-Q-9 After

Direction Photo

Taken: Northeast



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.170

Date: 8/12/02

Description:

Boundary Trench-Q-10 Before

Direction Photo

Taken: West



Photo No. B.171 **Date:** 8/12/02

Description: BT-Q-10



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.172

Date: 8/12/02

Description: BT-Q-10



Photo No. B.173

Date: 8/12/02

Description: BT-Q-10



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. **B.174**

Date: 8/12/02

Description:

Boundary Trench-Q-10

Direction Photo

Taken: West



Photo No. **B.175**

Date: 8/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. B.176

Date: 8/12/02

Description:

Boundary Trench-Q-10



Photo No. B.177 **Date:** 8/12/02

Description: BT-Q-10



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.178**

Date: 8/12/02

Description:

Boundary Trench-Q-10




Photo No. **B.179**

Date: 8/12/02

Description:Boundary Trench-Q-10 After

Direction Photo Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.180

Date: 6/19/02

Description:

Boundary Trench-R-1 Before

Direction Photo

Taken: East



Photo No. B.181 **Date:** 6/19/02


Description:

Boundary Trench-R-1 Before

Direction Photo

Taken:

North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.182

Date: 6/19/02

Description:

Boundary Trench-R-1 Before

Direction Photo

Taken: South



Photo No. B.183 **Date:** 6/19/02

Description:

BT-R-1

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.184**

Date: 6/19/02

Description:Boundary Trench-R-1





Photo No. **B.185**

Date: 6/19/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **B.186**

Date: 6/19/02

Description:

Boundary Trench-R-1



Direction Photo

Taken: North



Photo No. **B.187**


Date: 6/19/02

Description:

Boundary Trench-R-1

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.188

Date: 6/19/02

Description:

Boundary Trench-R-1




Photo No. B.189 **Date:** 6/19/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.190**

Date: 6/19/02

Description:Boundary Trench-R-1




Photo No. **B.191**

Date: 6/19/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. **B.192**

Date: 6/19/02

Description:

Boundary Trench-R-1



Photo No. **B.193**

Date: 6/19/02

Description:Boundary Trench-R-1 Decon



PHOTOGRAPHIC LOG

Client Name:Site Location:Project No.Sauget Area 2 GroupSauget, Illinois21560888

Photo No. B.194 6.

Date: 6/19/02

Description: BT-R-1 After

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:Site Location:Project No.Sauget Area 2 GroupSauget, Illinois21560888

Photo No. Date: 6/20/02

Description:

Boundary Trench-R-2 Before

Direction Photo Taken: South



Photo No. I

Date: 6/20/02

Description:

Boundary Trench-R-2 Before

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.197

Date: 6/20/02

Description:

Boundary Trench-R-2

Before

Direction Photo

Taken: South




Photo No. B.198 **Date:** 6/20/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No. 21560888

Photo No. B.199

Date: 6/20/02


Description:

Boundary Trench-R-2



Photo No. B.200 Date: 6/20/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.201**


Date: 6/20/02

Direction Photo

Taken:

East

Description:Boundary Trench-R-2
After



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. B.202

Date: 6/21/02

Description:

Boundary Trench-R-3 Before

Direction Photo Taken:

East





Photo No. B.203 Date: 6/21/02

Description:

Boundary Trench-R-3 Before

Direction Photo

Taken: North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **B.204**

Date: 6/21/02

Description:Boundary Trench-R-3





Photo No. **B.205**

Date: 6/21/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.206

Date: 6/21/02

Description:

Boundary Trench-R-3



Photo No. B.207 Date: 6/21/02

Description:

Boundary Trench-R-3 After

Direction Photo Taken:

North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888


Photo No. **B.208**

Date: 6/21/02

Description:
Boundary Trench-R-3
After

Direction Photo

Taken: East



PHOTOGRAPHIC LOG

Project No.

Client Name: Site Location:

Sauget Area 2 Group Sauget, Illinois 21560888

Photo No. Date: 6/20/02

Description:

Boundary Trench-R-4 Before

Direction Photo Taken:

East




Photo No. B.210 Date: 6/20/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.211 **Date:** 6/20/02

Description:

Boundary Trench-R-4



Photo No. B.212 **Date:** 6/20/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.213

Date: 6/20/02


Description:

Boundary Trench-R-4



Photo No. B.214 Date: 6/20/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.215

Date: 6/14/02

Description:

Site S - Concrete at American Bottoms before trackhoe is moved

Direction Photo Taken:

West




Photo No. B.216


Date: 6/14/02

Description:

Site S -Tracking Across Road

Direction Photo

Taken: North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.217

Date: 6/14/02

Description:

Site S/O -Tracking Across Road



Direction Photo Taken:

North




Photo No. B.218 **Date:** 6/14/02

Description:

Site O/S - Concrete at American Bottoms after trackhoe was moved

Direction Photo Taken:
Northwest



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.219

Date: 6/14/02

Description:

Site O/S – Concrete at American Bottoms after trackhoe was moved

Direction Photo

Taken: Northwest




Photo No. B.220

Date: 6/14/02

Description:

Site O/S – Concrete at American Bottoms after trackhoe was moved

Direction Photo Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888


Photo No. **B.221**

Date: 6/14/02

Description:Site O – Tracking across road

Direction Photo

Taken: Southwest



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. B.222

Date: 6/13/02

Description:

Boundary Trench-S-1 Before

Direction Photo Taken:

North



Photo No. B.223 **Date:** 6/13/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.224

Date: 6/13/02

Description:

Boundary Trench-S-1




Photo No. B.225 **Date:** 6/13/02

Description:

Boundary Trench-S-1

Direction Photo Taken: South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.226

Date: 6/13/02

Description:

Boundary Trench-S-1



Direction Photo

Taken: South



Photo No. B.227 Date: 6/13/02

Description:

Boundary Trench-S-1

Direction Photo Taken:

South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.228

Date: 6/13/02

Description:

Boundary Trench-S-1





Photo No. B.229 Date: 6/13/02

Description:

Boundary Trench-S-1 After

Direction Photo

Taken: South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Sauget, Illinois

21560888

Photo No. B.230

Date: 6/14/02

Description:

Boundary Trench-S-2 Before

Direction Photo

Taken: South



Photo No. B.231 **Date:** 6/14/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.232

Date: 6/14/02

Description:

Boundary Trench-S-2




Photo No. B.233 Date: 6/14/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illniois

Project No.

21560888

Photo No. **B.234**

Date:

6/14/02


Description:

Boundary Trench-S-2

After

Direction Photo Taken:

South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.235

Date: 6/13/02

Description:

Boundary Trench-S-3 Before

Direction Photo Taken:

West



Photo No. B.236

Date: 6/13/02

Description:

Boundary Trench-S-3

Direction Photo

Taken: South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Sauget, Illinois

21560888

Photo No. **B.237**

Date: 6/13/02

Description:

Boundary Trench-S-3




Photo No. **B.238**

Date: 6/13/02

Description:Boundary Trench-S-3

Direction Photo Taken: North



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.239

Date: 6/13/02

Description:

Boundary Trench-S-3



Photo No. B.240 **Date:** 6/13/02

Description:

Boundary Trench-S-3

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.241

Date: 6/13/02

Description:

Boundary Trench-S-3 After

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.242 **Date:** 6/14/02

Description:

Boundary Trench-S-4





Photo No. B.243 **Date:** 6/14/02

Description: BT-S-4



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. B.244 **Date:** 6/14/02

Description:

BT-S-4




Photo No. B.245

Date: 6/14/02

Description: BT-S-4



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. B.246

Date: 6/14/02

Description:

Boundary Trench-S-4



Photo No. B.247

Date: 6/14/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. B.248

Date: 6/14/02


Direction Photo

Taken:

West

Description:

Boundary Trench-S-4 After



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No.

Date: 8/14/02

Description:

Anomaly Trench-P-1

Before

Direction Photo

Taken: West



Photo No. C.2 **Date:** 8/14/02

Description:

Anomaly Trench -P-1

Before

Direction Photo

Taken: West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **C.3**

Date: 8/14/02


Description:Anomaly Trench -P-1



Photo No. **C.4**

Date: 8/14/02

Description:Anomaly Trench -P-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 8/14/02

Description:

Anomaly Trench-P-1




Photo No.

Date: 8/14/02

Description:

Anomaly Trench-P-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. **C.7**

Date: 8/14/02

Description:Anomaly Trench-P-1




Photo No. **C.8**

Date: 8/14/02

Description:

Anomaly Trench-P-1



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. C.9

Date: 8/14/02

Description:

Anomaly Trench-P-1





Photo No. C.10

Date: 8/14/02

Description:

Anomaly Trench-P-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.11

Date: 8/14/02

Description:Anomaly Trench-P-1



Photo No. **C.12**

Date: 8/14/02

Description:Anomaly Trench -P-1

Direction Photo Taken:

Northwest



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 8/14/02

Description:

Anomaly Trench-P-1 After

Direction Photo Taken:
Northwest




Photo No. C.14 **Date:** 8/14/02

Description:

Anomaly Trench-P-1 After

Direction Photo

Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. C.15

Date: 6/05/02

Description:

Anomaly Trench-Q-11

-11

Direction Photo

Taken: Northeast





Photo No. C.16

Date: 6/05/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **C.17**

Date: 6/05/02

Description:

Anomaly Trench-Q-11 After

Direction Photo Taken: North




Photo No. **C.18**

Date: 6/05/02

Description:

Anomaly Trench-Q-11 After

Direction Photo

Taken: East




Photo No. C.19 6/05/02

Description:
Anomaly Trench-Q-11
After

Direction Photo Taken:
South

PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. C.20

Date: 6/05/02

Description:

Anomaly Trench-Q-11

Direction Photo

Taken: North



Photo No. C.21

Date: 6/05/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Ilinois

Project No.

Photo No.

Date: 6/05/02

Description:

Anomaly Trench-Q-11

21560888

Direction Photo

Taken:
East




Photo No. C.23

Date: 6/05/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. C.24

Date: 6/05/02

Description:

Anomaly Trench-Q-11



Photo No. C.25

Date: 6/05/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.26

Date: 6/05/02

Description:

Anomaly Trench-Q-11




Photo No. C.27 Date: 6/05/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. **C.28**

Date: 6/05/02

Description:Anomaly Trench-Q-11




Photo No. C.29

Date: 6/05/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 6/05/02

Description:

Anomaly Trench-Q-11



Photo No. C.31 Date: 6/05/02

Description:

Anomaly Trench-Q-11

Direction Photo Taken:
Northeast



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. C.32

Date: 6/05/02

Description:

Anomaly Trench-Q-11 Before

Direction Photo Taken:

North




Photo No. C.33

Date: 6-5-02

Description:

Anomaly Trench-Q-11 Before

Direction Photo





PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No. C.34

Date: 6/05/02

Description:

Anomaly Trench-Q-11 Before

Direction Photo Taken: South




Photo No. C.35

Date: 6/05/02

Description: Anomaly Trench-Q-11

Direction Photo Taken: Southwest



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. C.36

Date: 6/06/02

Description:

Anomaly Trench-Q-12 Before

Direction Photo Taken:
North




Photo No. C.37

Date: 6/06/02

Description:

Anomaly Trench-Q-12 Before

Direction Photo

Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **C.38**

Date: 6/06/02

Description:

Anomaly Trench-Q-12


Direction Photo

Taken: West

Photo No. C.39

Date: 6/06/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.40

Date: 6/06/02

Description:Anomaly Trench-Q-12



Photo No. C.41

Date: 6/06/02

Description:Anomaly Trench-Q-12



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

Photo No. C.42

Date: 6/06/02

Description:

Anomaly Trench-Q-12

21560888

Direction Photo

Taken:

Northwest



Photo No. C.43 Date: 6/06/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No.

Date: 6/06/02

Description:

Anomaly Trench-Q-12




Photo No. C.45

Date: 6/06/02


Description:

Anomaly Trench-Q-12

Direction Photo

Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.46

Date: 6/06/02

Description:Anomaly Trench-Q-12




Photo No. C.47

Date: 6/06/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No.

Date: 6/06/02

Description:

Anomaly Trench-Q-12

21560888

Direction Photo

Taken:

Northwest




Photo No. C.49 **Date:** 6/06/02

Description:

Anomaly Trench-Q-12

Direction Photo Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.50

Date: 6/06/02

Description:


Anomaly Trench-Q-12



Photo No. C.51

Date: 6/06/02

Description:Anomaly Trench-Q-12



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.52

Date: 6/06/02

Description:

Anomaly Trench-Q-12



Photo No. C.53

Date: 6/06/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illniois

Project No.

21560888

Photo No. C.54

Date:

Description:Anomaly Trench-Q-12





Photo No. C.55

Date: 6/06/02

Description:Anomaly Trench-Q-12



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No. C.56

Date: 6/06/02

Description:

Anomaly Trench-Q-12




Photo No. C.57

Date: 6/06/02

Description:

Anomaly Trench-Q-12 After

Direction Photo Taken: Northwest



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illniois

Project No.

21560888

Photo No. C.58

Date: 6/06/02

Description:

Anomaly Trench-Q-12

After

Direction Photo

Taken:

East



Photo No. C.59

Date: 6/06/02

Description:

Anomaly Trench-Q-12 After

Direction Photo

Taken: South



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **C.60**

Date: 6/06/02

Description:

Anomaly Trench-Q-13

Before

Direction Photo

Taken: West



Photo No. C.61


Date: 6/06/02

Description:

Anomaly Trench-Q-13 **Before**

Direction Photo Taken:

North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.62

Date: 6/06/02

Description:Anomaly Trench-Q-13




Photo No. **C.63**

Date: 6/06/02

Description:

Anomaly Trench-Q-13

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.64

Date: 6/06/02

Description:

Anomaly Trench-Q-13

Direction Photo

Taken: East





Photo No. **C.65**

Date: 6/06/02

Description:Anomaly Trench-Q-13



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. C.66

Date: 6/06/02

Description:


Anomaly Trench-Q-13



Photo No. C.67

Date: 6/06/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No. **C.68**

Date: 6/06/02

Description:

Anomaly Trench-Q-13




Photo No. C.69

Date: 6/06/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.70

Date: 6/06/02

Description:Anomaly Trench-Q-13





Photo No. C.71

Date: 6/06/02

Description:Anomaly Trench-Q-13



Client Name: Sauget Area 2 Group Photo No. C.72 | 6/06/02 Description: Anomaly Trench-Q-13

Photo No. C.73

Date: 6/06/02

Description:

Anomaly Trench-Q-13

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

Photo No.

Date: 6/06/02

Description:

Anomaly Trench-Q-13

21560888

Direction Photo

Taken:

West



Photo No. C.75 Date: 6/06/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.76

Date: 6/06/02

Description:

Anomaly Trench-Q-13





Photo No. C.77 **Date:** 6/06/02

Description:

Anomaly Trench-Q-13

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illniois

Project No.

21560888

Photo No. C.78

Date: 6/06/02

Description:

Anomaly Trench-Q-13

After

Direction Photo

Taken: West





Photo No. C.79

Date: 6/06/02

Description:

Anomaly Trench-Q-13 After

Direction Photo Taken: North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **C.80**

Date: 6/11/02

Description:

Anomaly Trench-Q-14

Before

Direction Photo

Taken: North



Photo No. C.81

Date: 6/11/02

Description:

Anomaly Trench-Q-14 Before

Direction Photo Taken: Southwest



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No. 21560888

Photo No. **C.82**

Date: 6/11/02

Description:

Anomaly Trench-Q-14




Photo No. **C.83**

Date: 6/11/02

Description:Anomaly Trench-Q-14



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No.

Date: 6/11/02

Description:

Anomaly Trench-Q-14

21560888

Direction Photo

Taken: North




Photo No. C.85 **Date:** 6/11/02

Description:

Anomaly Trench-Q-14

Direction Photo Taken: Northeast



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 6/11/02

Description:

Anomaly Trench-Q-14





Photo No. C.87 **Date:** 6/11/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 6/11/02

Description:

Anomaly Trench-Q-14



Photo No.

Date: 6/11/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illniois

Project No.

21560888

Photo No.

Date: 6/11/02

Description:

Anomaly Trench-Q-14

Direction Photo

Taken: North




Photo No.

Date: 6/11/02

Description:

Anomaly Trench-Q-14

Direction Photo Taken:
Northeast



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.92

Date: 6/11/02

Description:

Anomaly Trench-Q-14

Direction Photo

Taken: West




Photo No. C.93

Date: 6/11/02

Description:

Anomaly Trench-Q-14

After

Direction Photo Taken:

North



PHOTOGRAPHIC LOG


Site Location: Project No. **Client Name:** Sauget Area 2 Group

Photo No. Date: C.94

6/11/02

Description: Anomaly Trench-Q-14 After

Direction Photo Taken: West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. C.95

Date: 6/07/02

Description:

Anomaly Trench-Q-15 Before

Direction Photo

Taken: East




Photo No. C.96

Date: 6/07/02

Description:

Anomaly Trench-Q-15 Before

Direction Photo Taken:
Northeast



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.97

Date: 6/07/02

Description:

Anomaly Trench-Q-15





Photo No.

Date: 6/07/02

Description:

Anomaly Trench-Q-15

Direction Photo Taken: Northeast



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location: Sauget, Illinois Project No. 21560888

Date:

6/07/02

C.99 Description:

Photo No.

Anomaly Trench-Q-15



Photo No. C.100

Date: 6/07/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.101

Date: 6/07/02

Description:

Anomaly Trench-Q-15




Photo No. C.102

Date: 6/07/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. C.103

Date: 6/07/02


Description:

Anomaly Trench-Q-15



Photo No. C.104 **Date:** 6/07/02

Description:



PHOTOGRAPHIC LOG

Client Name: Site Location: Project No.

Sauget Area 2 Group Sauget, Illinois 21560888

Photo No. Date:

C.105 6/07/02

Description:Anomaly Trench-Q-15



Photo No. C.106 Date: 6/07/02
Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. C.107

Date: 6/07/02

Description:

Anomaly Trench-Q-15





Photo No. C.108

Date: 6/07/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location: Sauget, Illinois

Project No. 21560888

Photo No. C.109

Date: 6/07/02

Description: Anomaly Trench-Q-15

Photo No. C.110

Date: 6/07/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.111

Date: 6/07/02

Description:

Anomaly Trench-Q-15





Photo No. C.112

Date: 6/07/02

Description:Anomaly Trench-Q-15



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.113

Date:

6/07/02

Description:

Anomaly Trench-Q-15



Photo No. C.114

Date: 6/07/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.115

Date: 6/07/02

Description:

Anomaly Trench-Q-15

After

Direction Photo

Taken: North




Photo No. C.116 Date: 6/07/02

Description:

Anomaly Trench-Q-15

After

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.117

Date: 6/11/02

Description:

Anomaly Trench-Q-16 Before

Direction Photo

Taken: Southwest



Photo No.

Date: 6/11/02

Description:

Anomaly Trench-Q-16 Before

Direction Photo Taken:

South



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.119

Date: 6/11/02

Description:

Anomaly Trench-Q-16



Photo No. C.120 Date: 6/11/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

Photo No. C.121

Date: 6/11/02

Description:

Anomaly Trench-Q-16

21560888

Direction Photo Taken:

East



Photo No. C.122

Date: 6/11/02

Description:

Anomaly Trench-Q-16

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No. C.123

Date: 6/11/02

Description:

Anomaly Trench-Q-16

21560888



Taken:

East



Photo No. C.124 **Date:** 6/11/02

Description:

Anomaly Trench-Q-16

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.125

Date: 6/11/02

Description:

Anomaly Trench-Q-16

2100000

Direction Photo Taken:

West



Photo No. C.126

Date: 6/11/02

Description:

Anomaly Trench-Q-16 After

Direction Photo Taken:

Southwest



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.127

Date: 6/11/02

Description:
Anomaly Trench-Q-16
After

Direction Photo

Taken: Southwest



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No. C.128

Date: 8/12/02

Description:

Anomaly Trench-Q-18 Before

Direction Photo

Taken: East



Photo No. C.129

Date: 8/12/02

Description:

Anomaly Trench-Q-18 Before

Direction Photo Taken:

North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 8/12/02

Description:

Anomaly Trench-Q-18

Direction Photo Taken:

West



Photo No.

Date: 8/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No. C.132

Date: 8/12/02

Description:

Anomaly Trench-Q-18

21560888

Direction Photo

Taken: West



Photo No. C.133

Date: 8/12/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.134

Date: 8/12/02

Description:Anomaly Trench-Q-18




Photo No. C.135

Date: 8/12/02

Description:Anomaly Trench-Q-18



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.136

Date: 8/12/02

Description: Anomaly Trench-Q-18 After

Direction Photo

Taken: Northwest



Photo No. C.137

Date: 8/12/02

Description:

Anomaly Trench-Q-18

Direction Photo





PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. C.138

Date: 8/13/02

Description:

Anomaly Trench-R-1 Before

20.0.0

Direction Photo

Taken: North




Photo No. C.139

Date: 8/13/02

Description:

Anomaly Trench-R-1 Before

Direction Photo Taken: Northwest



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. C.140

Date: 8/13/02

Description:

Anomaly Trench-R-1

1

Direction Photo

Taken: East



Photo No. C.141 **Date:** 8/13/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. C.142

Date: 8/13/02

Description:Anomaly Trench-R-1




Photo No. C.143

Date: 8/13/02

Description:Anomaly Trench-R-1



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 8/13/02

Description:

Anomaly Trench-R-1



Photo No. C.145

Date: 8/13/02

Description:



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location: Sauget, Illinois

Project No.

21560888

Photo No. C.146

Date: 8/13/02

Description:

Anomaly Trench-R-1




Photo No. C.147

Date: 8/13/02

Description:Anomaly Trench-R-1



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. C.148

Date: 8/13/02

Description:

Anomaly Trench-R-1



Photo No. C.149

Date: 8/13/02

Description:

Anomaly Trench-R-1 After

Direction Photo

Taken: South



Photo No. C.150 B/13/02

Description:
Anomaly Trench-R-1
After

Direction Photo
Taken:
South

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.151

Date: 8/14/02

Description:

Anomaly Trench-S-1

Before

Direction Photo Taken: North



Photo No. C.152

Date: 8/14/02

Description:

Anomaly Trench-S-1

Before

Taken:

Direction Photo North



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. C.153

Date: 8/14/02

Description:

Anomaly Trench-S-1



Photo No. C.154 Date: 8/14/02

Description: Anomaly Trench-S-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.155

Date: 8/14/02

Description:Anomaly Trench-S-1



Photo No. C.156

Date: 8/14/02

Description: Anomaly Trench-S-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. C.157 Date: 8/14/02

Description:

Anomaly Trench-S-1



Photo No. C.158 Date: 8/14/02

Description:

Anomaly Trench-S-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. C.159

Date: 8/14/02

Description:

Anomaly Trench-S-1



Photo No. C.160

Date: 8/14/02

Description:

Anomaly Trench-S-1



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 8/14/02

Description:

Anomaly Trench-S-1



Photo No. C.162 **Date:** 8/14/02

Description:

AT-S-1 After

Direction Photo Taken:

East



Photo No. C.163 Date: 8/14/02

Description: Anomaly Trench-S-1 After

Direction Photo Taken: East



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/2/02

Description:


Waste-O-1 (0-4')



Photo No. Date: 7/2/02

Description:

Waste-O-1 (4-8')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **D.3**

Date: 7/2/02

Description:

Waste-O-1 (8-12')



Photo No. D.4

Date: 7/2/02

Description:

Waste-O-1 (12-16')




URS Client Name: Sauget Area 2 Group Site Location: Sauget, Illinois Project No. 21560888

Photo No. Date: 7/2/02

Description:

Waste-O-1 (16-20')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **D.6**

Date: 7/1/02

Description:

Waste-O-2 (4-8')



Photo No. **D.7**

Date: 7/1/02

Description:

Waste-O-2 (8-12')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. **D.8**

Date: 7/1/02

Description:

Waste-O-2 (12-16')




Photo No.

D.9

Date: 7/1/02

Description:

Waste-O-2 (16-20')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/1/02

Description:

Waste-O-3 (4-8')





Photo No. D.11 Date: 7/1/02

Description:

Waste-O-3 (8-12')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. D.12

Date: 7/1/02

Description:

Waste-O-3 (12-16')





Photo No. D.13 **Date:** 7/1/02

Description:

Waste-O-3 (16-20')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. D.14

Date: 7/16/02

Description:


Waste-P-1 (0-4')



Photo No. Date: 7/16/02

Description:

Waste-P-1 (4-5.5')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/16/02

Description:

Waste-P-1 (12-15.5')



Photo No. D.17 **Date:** 7/16/02

Description:

Waste-P-1 (0-7') Offset location, began using Sonic rig



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. D.18

Date: 7/16/02

Description:

Waste-P-1 (7-17')





Photo No. D.19 **Date:** 7/16/02

Description:

Waste-P-1 (17-27')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/16/02

Description:

Waste-P-1 (17-27')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/02/02

Description:

Waste-P-2 (4-8')




Photo No. Date: 7/02/02

Description:

Waste-P-2 (8-10')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. D.23

Date: 7/16/02

Description:

Waste-P-2 (0-2') Offset location, began using Sonic rig




Photo No. D.24

Date: 7/16/02

Description:

Waste-P-2 (2-4')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. **D.25**

Date: 7/16/02

Description:

Waste-P-2 (4-5')





Photo No. Date: 7/16/02 **D.26** Description:

Waste-P-2 (5-13')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No. 21560888

Photo No.

Date:

D.27 7/16/02

Description:

Waste-P-2 (13-17')




Photo No. Date: **D.28**

7/16/02

Description:

Waste-P-2 (20-30')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.


21560888

Photo No. D.29 7

Date: 7/16/02

Description:

Waste-P-2 (30-40')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Sauget, Illinois

21560888

Photo No. **D.30**

Date: 7/17/02

Description: Waste-P-3 (0-4')




Photo No.

Date: 7/17/02 **D.31**

Description:

Waste-P-3 (0-7') Offset location, began using Sonic rig



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. D.32

Date: 7/17/02

Description:

Waste-P-3 (7-17')





Photo No. D.33

Date: 7/17/02

Description:

Waste-P-3 (17-27')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois


21560888

Photo No. D.34

Date: 7/17/02

Description:

Waste-P-3 (17-27')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. D.35

Date: 7/8/02

Description:

Waste-P-4 (0-4')





Photo No. D.36 **Date:** 7/8/02

Description:

Waste-P-4 (0-4') – INCORRECTLY LABELED 4-8



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. D.37

Date: 7/8/02

Description:

Waste-P-4 (0-6') Offset location, began using Sonic rig




Photo No. D.38

Date: 7/8/02

Description:

Waste-P-4 (6-16')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. D.39

Date: 7/8/02

Description:

Waste-P-4 (16-26')



Photo No. D.40

Date: 7/8/02

Description:

Waste-P-4 (16-26')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. D.41

Date: 7/26/02

Description:

Waste-Q-1 (0-7')



Photo No. D.42

Date: 7/26/02

Description:

Waste-Q-1 (7-17')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/26/02 **D.43**

Description: Waste-Q-1 (7-17')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. D.44

Date: 7/18/02

Description: Waste-Q-2



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. D.45

Date: 7/17/02

Description:


Waste-Q-3 (0-7')



Photo No. D.46 Date: 7/17/02

Description:

Waste-Q-3 (0-7')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No. 21560888

Sauget Area 2 Group

Sauget, Illinois

Photo No. Date: 7/17/02 **D.47**

Description: Waste-Q-3 (7-17')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. D.48

Date: 7/18/02

Description:

Waste-Q-4 (0-7')



Photo No. D.49

Date: 7/18/02

Description:

Waste-Q-4 (7-13')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. Date: **D.50** 7/18/02

Description: Waste-Q-4 (13-17')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No.

Date: **D.51** 7/17/02

Description:

Waste-Q-5 (0-7')




Photo No. **D.52**

Date: 7/17/02

Description:

Waste-Q-5 (0-7')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No.

Date: 7/17/02

D.53 Description:

Waste-Q-5 (7-17')




Photo No. **D.54**

Date: 7/17/02

Description:

Waste-Q-5 (7-17')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/19/02

Description: Waste-Q-6 (0-4')





Photo No. D.56 **Date:** 7/19/02

Description: Waste-Q-6 (4-7')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/19/02 **D.57**

Description:

Waste-Q-6 (7-15')



Photo No. **D.58**

Date: 7/19/02

Description:

Waste-Q-6 (15-18')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. D.59

Date: 7/19/02

Description:

Waste-Q-7 (0-4')




Photo No. D.60 **Date:** 7/19/02

Description:

Waste-Q-7 (6-16')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois


Project No.

21560888

Photo No. **D.61**

Date: 7/19/02

Description: Waste-Q-7 (16-26')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **D.62**

Date: 7/19/02

Description:

Waste-Q-8 Set-up

Direction Photo

Taken: North



Photo No. **D.63**

Date: 7/19/02

Description:

Waste-Q-8 (0-6')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. D.64

Date: 7/19/02

Description:

Waste-Q-8 (6-10')





Photo No. D.65 **Date:** 7/19/02

Description:

Watse-Q-8 (10-18')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group


Sauget, Illinois

21560888

Photo No. **D.66**

Date: 7/19/02

Description: Waste-Q-8 (18-28')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. D.67

Date: 7/26/02

Description:

Waste-Q-9 (0-5')




Photo No. D.68

Date: 7/26/02

Description:

Waste-Q-9 (5-10')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. D.69

Date: 7/26/02

Description:

Waste-Q-9 (10-25')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. D.70

Date:

D.70 7/26/02

Description:

Waste-Q-10 (0-7')





Photo No. D.71

Date: 7/26/02

Description:

Waste-Q-10 (7-17')



Client Name: Sauget Area 2 Group Site Location: Sauget, Illinois Project No. 21560888 Photo No. D.72 Description: Waste-Q-10 (17-27')

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. **D.73**

Date: 7/22/02

Description:

Waste-Q-11 (0-7')




Photo No. **D.74**

Date: 7/22/02

Description:

Waste-Q-11 (7-17')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No.

Date:

D.75 7/22/02

Description:

Waste-Q-12 (0-6')




Photo No. **D.7**6

Date: 7/22/02

Description:

Waste-Q-12 (0-6')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **D.77**

Date: 7/11/02

Description: Waste-R-1



Photo No. **D.78**

Date: 7/11/02

Description: Waste-R-1 (0-4')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **D.79**

Date: 7/11/02

Description: Waste-R-1 (4-8')





Photo No. **D.80**

Date: 7/11/02

Description: Waste-R-1 (8-12')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. **D.81**

Date: 7/11/02


Description: Waste-R-1 (12-16')



Photo No. **D.82**

Date: 7/11/02

Description: Waste-R-1 (16-20')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois


Project No.

21560888

Photo No. **D.83**

Date: 7/11/02

Description: Waste-R-1 (20-24')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **D.84**

Date:

7/11/02

Description: Waste-R-2




Photo No. **D.85**

Date: 7/11/02

Description: Waste-R-2



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. D.86

Date: 7/11/02

Description: Waste-R-2



Photo No. D.87 Date: 7/11/02

Description: Waste-R-2



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois


Project No.

21560888

Photo No. Date: 7/11/02

Description:

Waste-R-2 (12-16')






Photo No. D.89

Date: 7/11/02

Description:

Waste-R-2 (20-24')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. D.90

Date: 7/12/02

Description:

Waste-R-3

Direction Photo Taken:

Southwest



Photo No. D.91

Date: 7/12/02

Description:

Waste-R-3

Direction Photo

Taken:

Southwest



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date:

D.92 7/

7/12/02

Description:

Waste-R-3

Direction Photo

Taken: West



Photo No. D.93

Date: 7/12/02

Description:

Waste-R-3

Direction Photo Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **D.94**

Date: 7/12/02

Description:

Waste-R-3

Direction Photo

Taken:


Southwest



Photo No. D.95

Date: 7/12/02

Description: Waste-R-3 (0-4')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **D.96**

Date:

7/12/02

Description: Waste-R-3





Photo No. **D.97**

Date: 7/12/02

Description: Waste-R-3



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. D.98

Date: 7/12/02

Description: Waste-R-3




Photo No. D.99 Date: 7/12/02

Description: Waste-R-3



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Photo No.

Date:

D.100 7/12/02

Description: Waste-R-4 (0-4')



Photo No. D.101 **Date:** 7/12/02

Description: Waste-R-4 (4-8')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. D.102

Date:

7/12/02


Description: Waste-R-4 (8-12')



Photo No. D.103

Date: 7/12/02

Description: Waste-R-4 (12-16')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. D.104

Date: 7/12/02

Description:

Waste-R-4 (16-20')





Photo No. D.105

Date: 7/12/02

Description:

Waste-R-4 (20-24')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No. D.106

Date: 7/12/02

Description: Waste-R-4 (24-28')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **D.107**

Date: 7/1/02

Description: Waste-S-1

Direction Photo Taken:

West




Photo No. D.108

Date: 7/1/02

Description: Waste-S-1 (0-2')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. D.109

Date: 7/1/02

Description:

Waste-S-1 (2-4')



Photo No. D.110

Date: 7/1/02

Description: Waste-S-1 (4-6')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/1/02

Description:

Waste-S-1 (6-8')





Photo No. D.112

Date: 7/1/02

Description:

Waste-S-1 (8-12') – INCORRECTLY LABELED AS 12-16'



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois


21560888

Photo No. D.113

Date: 7/1/02

Description:

Waste-S-1 (12-16')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date:

7/1/02

D.114

Description: Waste-S-2 (0-4')



Photo No. D.115

Date: 7/1/02

Description: Waste-S-2 (4-8')



Client Name: Sauget Area 2 Group Photo No. D.116 7/1/02 Description: Waste-S-2 (8-12') PHOTOGRAPHIC LOG Project No. 21560888 Project No. 21560888

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. E.1

Date: 7/25/02

Description:

Leach-O-1 (0-5')




Photo No.

Date: 7/25/02 **E.2**

Description:

Leach-O-1 (5-15')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group


Sauget, Illniois

21560888

Photo No. **E.3**

Date: 7/25/02

Description: Leach-O-1 (5-15')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. **E.4**

Date: 7/25/02

Description:

Leach-P-1 (5-15')





Photo No. **E.5**

Date: 7/25/02

Description: Leach-P-1 (15-25')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. E.6

Date: 7/25/02

Description:

Leach-P-1 (15-25')





Photo No. E.7 Date: 7/25/02

Description:

Leach-P-1 (25-30')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 7/26/02

Description:

Leach-Q-1 (6-12')




Photo No. E.9 Date: 7/26/02

Description:

Leach-Q-1 (6-12')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location: Sauget, Illinois Project No.

21560888

Photo No. E.10 Date: 7/26/02

Description:

Leach-Q-2 (0-6')





Photo No. E.11

Date: 7/26/02

Description:

Leach-Q-2 (6-16')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. E.12

Date: 7/26/02

Description:

Leach-Q-2 (6-16')




Photo No. E.13 Date: 7/26/02

Description: Leach-Q-2 After



URS Client Name: Sauget Area 2 Group Site Location: Sauget, Illinois Project No. 21560888

Photo No. E.14

Date: 7/26/02

Description: Leach-Q-2 After

Direction Photo Taken: South



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. E.15

Date: 7/26/02

Description: Leach-Q-3 (0-9')





Photo No. Date: 7/26/02

Description: Leach-Q-3 (0-9')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. E.17

Date: 7/25/02

Description: Leach-R-1

Direction Photo

Taken: West




Photo No. E.18

Date: 7/25/02

Description:

Leach-R-1 (0-5')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. E.19

Date: 7/25/02

Description:

Leach-R-1 (5-15')




Photo No. E.20

Date: 7/25/02

Description:

Leach-R-1 (15-22')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **E.21**

Date: 7/25/02

Description: Leach-S-1 (0-7')-1st location




Photo No. **E.22**

Date: 7/25/02

Description: Leach-S-1 (0-7')-1st location



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. E.23

Date: 7/25/02

Description:

Leach-S-1 (0-7')-1st location



Photo No. E.24

Date: 7/25/02

Description:

Leach-S-1 (0-7')-2nd location



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. E.25 **Date:** 7/25/02

Description:

Leach-S-1 (7-12')-2nd location





Photo No. Date: 7/25/02

Description:

Leach-S-1 (7-12')-2nd location



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. F.1

Date: 7/26/02

Description:Well Sampling
Leachate-Q-1





Photo No. **F.2**

Date: 7/26/02

Description: Well Sampling Leachate-Q-1



Client Name: Sauget Area 2 Group Photo No. F.3 7/26/02 Description: Well Sampling Leachate-Q-1

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **G.1**

Date: 7/2/02

Description:

BDRK-O-1 Set up

Direction Photo

Taken:

South




Photo No. **G.2**

Date: 7/2/02

Description:

BDRK-O-1 (5-10')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/2/02

Description:

BDRK-O-1 (5-15')




Photo No.

Date: 7/2/02

Description:

BDRK-O-1 (15-25')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 7/2/02

Description:

BDRK-O-1 (25-35')




Photo No. G.6

Date: 7/2/02

Description:

BDRK-O-1 (35-55')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **G.7**

Date: 7/2/02

Description:

BDRK-O-1 (55-75')




Photo No.

Date: 7/2/02 **G.8**

Description:

BDRK-O-1 (75-85')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **G.9**

Date: 7/2/02

Description:

BDRK-O-1 (85-95')




Photo No. I

Date: 7/2/02

Description:

BDRK-O-1 (5-105')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/2/02

Description:

BDRK-O-1 (105-115')




Photo No. Date: 7/2/02

Description:

BDRK-O-1 (105-115')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. G.13

Date: 7/2/02

Description:


BDRK-O-1 (115-125')



Photo No. Date: 7/2/02

Description:

BDRK-O-1 (115-125')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/11/02

Description:

BDRK-P-1

Direction Photo

Taken: East




Photo No. G.16

Date: 7/11/02

Description:

BDRK-P-1 (15-25')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illniois

Project No.

21560888

G.17

Photo No. Date: 7/11/02

Description:


BDRK-P-1 (15-25')



Photo No. Date: 7/11/02 **G.18**

Description:

BDRK-P-1 (25-35')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No. **G.19**

Date: 7/11/02

Description:

BDRK-P-1 (35-55')





Photo No. Date: 7/11/02 **G.20**

Description:

BDRK-P-1 (55-75')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 7/11/02

Description:

BDRK-P-1 (55-75')





Photo No. Date: 7/11/02

Description:

BDRK-P-1 (75-95')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. G.23

Date: 7/11/02

Description:

BDRK-P-1 (75-95')





Photo No. G.24 **Date:** 7/11/02

Description:

BDRK-P-1 (95-115')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Date:

Sauget, Illinois

21560888

Photo No. **G.25**

7/11/02 Description:

BDRK-P-1 (95-115')




Photo No. **G.26**

Date: 7/11/02

Description:

BDRK-P-1 (115-125')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/11/02

Description:

BDRK-P-1 (115-125')




Photo No. G.28

Date: 7/11/02

Description:

BDRK-P-1 (125-130')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. G.29

Date: 7/11/02

Description:


BDRK-P-1 (130-135')



Photo No. G.30 **Date:** 7/11/02

Description:

BDRK-P-1 (130-135')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **G.31**

Date: 7/11/02

Description:


BDRK-P-1 (135-145')



Photo No. G.32 **Date:** 7/11/02

Description:

BDRK-P-1 (145-159')



PHOTOGRAPHIC LOG

Client Name:Site Location:Project No.Sauget Area 2 GroupSauget, Illinois21560888

Photo No. Date: 7/11/02

Description: BDRK-P-1 After


Direction Photo Taken: West



Photo No. Date: 7/11/02

Description:BDRK-P-1 After

Direction Photo Taken: East



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. G.35

Date: 7/9/02

Description:


BDRK-Q-1 (5-15')



Photo No. Date: 7/9/02

Description:

BDRK-Q-1 (15-25')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/9/02

Description:

BDRK-Q-1 (25-35')




Photo No. Date: 7/9/02

Description:

BDRK-Q-1 (55-75')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. Date: 7/9/02

Description:

BDRK-Q-1 (107-108')




Photo No. G.40

Date: 7/9/02

Description:

BDRK-Q-1 (108-115')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. D

Date: 7/9/02

Description:

BDRK-Q-1 (115-135')




Photo No. G.42

Date: 7/9/02

Description:

BDRK-Q-1 (115-135')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. G.43

Date: 7/9/02

Description:

BDRK-Q-1 (115-135')





Photo No. Date: 7/9/02

Description:

BDRK-Q-1 (135-140')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. G.45

Date: 7/9/02

Description:

BDRK-Q-1 (140-150')




Photo No. G.46

Date: 7/9/02

Description:

BDRK-Q-1 (150-163')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **G.47**

Date: 7/15/02

Description: BDRK-Q-2

Direction Photo

Taken:

North



Photo No. Date: 7/15/02 **G.48**

Description: BDRK-Q-2

Direction Photo Taken: Northeast



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. G.49

Date: 7/15/02

Description: BDRK-Q-2

Direction Photo Taken:

North





Photo No. **G.50**

Date: 7/15/02

Description: BDRK-Q-2



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **G.51**

Date: 7/15/02

Description:

BDRK-Q-2

Direction Photo Taken:

Northeast





Photo No. **G.52**

Date: 7/15/02

Description: BDRK-Q-2 (0-5')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. G.53

Date: 7/15/02

Description:

BDRK-Q-2 (5-15')





Photo No. G.54 Date: 7/15/02

Description:

BDRK-Q-2 (15-35')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **G.55**

Date: 7/15/02

Description:

BDRK-Q-2 (35-55')





Photo No. G.56

Date: 7/15/02

Description:

BDRK-Q-2 (55-75')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. G.57

Date: 7/15/02

Description:

BDRK-Q-2 (55-75')





Photo No. G.58

Date: 7/15/02

Description:

BDRK-Q-2 (75-95')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

G.59

Photo No. Date: 7/15/02

Description:

BDRK-Q-2 (75-95')




Photo No. **G.60**

Date: 7/15/02

Description:

BDRK-Q-2 (95-115')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No. 21560888

Photo No. G.61

Date:

7/15/02

Description:

BDRK-Q-2 (95-115')




Photo No. **G.62**

Date: 7/15/02

Description: BDRK-Q-2 (95-115')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **G.63**

Date: 7/15/02

Description:

BDRK-Q-2 (115-125')





Photo No. G.64

Date: 7/15/02

Description:

BDRK-Q-2 (115-125')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. [

Date: 7/15/02

Description:

BDRK-Q-2 (125-135')



Photo No. Date: 7/15/02

Description:

BDRK-Q-2 (135-143')



PHOTOGRAPHIC LOG

Project No.

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois 21560888

Photo No. G.67

Date: 7/15/02

Description: BDRK-Q-2 After

Direction Photo Taken:

North



Photo No. G.68 **Date:** 7/15/02

Description:BDRK-Q-2 After

Direction Photo Taken: North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 7-3-02

Description: BDRK-R-1

Direction Photo

Taken:

South



Photo No. G.70 **Date:** 7-3-02

Description: BDRK-R-1

Direction Photo Taken:

North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. G.71 **Date:** 7-3-02

Description: BDRK-R-1




Photo No. G.72 **Date:** 7-3-02

Description: BDRK-R-1



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

Photo No. **G.73**

Date:

7-3-02

Description: BDRK-R-1

21560888

Direction Photo

Taken:

South




Photo No. **G.74**

Date: 7-3-02

Description:

BDRK-R-1 (0-5')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. G.75 **Date:** 7-3-02

Description:

BDRK-R-1 (5-15')




Photo No. Date: 7-3-02
Description:

Description: BDRK-R-1 (15-25')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 7-3-02

G.77 7-3-0

Description:

BDRK-R-1 (25-35')





Photo No. G.78 Date: 7-3-02

Description:

BDRK-R-1 (35-45')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. G.79

Date: 7-3-02

Description:

BDRK-R-1 (35-55')



Photo No. G.80 **Date:** 7-3-02

Description:

BDRK-R-1 (55-75')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. G.81

Date: 7-3-02

Description:

BDRK-R-1 (55-75')



Photo No. Date: 7-3-02

Description:

BDRK-R-1 (75-95')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No. **G.83**

Date:

7-3-02

Description:

BDRK-R-1 (95-115')




Photo No. **G.84**

Date: 7-3-02

Description:

BDRK-R-1 (95-115')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. G.85

Date: 7-3-02

Description:

BDRK-R-1 (95-115')



Photo No. Date: 7-3-02

Description:

BDRK-R-1 (115-135')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. Date: 7-3-02

Description:

BDRK-R-1 (115-135')



Photo No. G.88 **Date:** 7-3-02

Description:

BDRK-R-1 (135-140')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.


21560888

Photo No. **G.89**

Date: 7-3-02


Description:

BDRK-R-1 (140-150')



Description:

BDRK-R-1 (150-163')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. **G.91**

Date: 7-3-02

Description:

BDRK-R-1 (150-163')




Photo No.


Date: 7-3-02 **G.92**

Description:

BDRK-R-1 After

Direction Photo Taken:

South



URS PHOTOGRAPHIC LOG Project No. Client Name: Site Location: Sauget Area 2 Group Sauget, Illinois 21560888 Photo No. Date: **G.93** 7-3-02 Description: BDRK-R-1 After **Direction Photo** Taken: North

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **G.94**

Date: 6/26/02

Description:

BDRK-S-1

Direction Photo

Taken: North




Photo No. **G.95**

Date: 6/26/02

Description: BDRK-S-1

Direction Photo Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **G.96**

Date: 6/26/02

Description:

BDRK-S-1

Direction Photo

Taken: North




Photo No. **G.97**

Date: 6/26/02

Description: BDRK-S-1

Direction Photo

Taken: West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. G.98

Date: 6/26/02

Description: BDRK-S-1

Direction Photo Taken:

West



Description: BDRK-S-1

Direction Photo Taken: South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: **G.100** 6/26/02

Description: BDRK-S-1

Direction Photo Taken:

West





Photo No. G.101

Date: 6/26/02

Description: BDRK-S-1

Direction Photo Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. G.102

Date: 6/26/02

Description: BDRK-S-1



Photo No. G.103

Date: 6/26/02

Description: BDRK-S-1



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No. 21560888

Photo No. G.104

Date: 6/26/02

Description:

BDRK-S-1 (0-5')





Photo No. Date: 6/26/02

Description:

BDRK-S-1 (5-15')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Sauget, Illinois

21560888

Photo No. G.106

Date: 6/26/02

Description:

BDRK-S-1 (15-25')




Photo No. G.107 **Date:** 6/26/02

Description:

BDRK-S-1 (25-35')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. G.108

Date: 6/26/02

Description:

BDRK-S-1 (35-45')





Photo No. Date: 6/26/02

Description: BDRK-S-1 (35-45')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. Date: 6/26/02

Description:


BDRK-S-1 (35-45')



Photo No. Date: 6/26/02

Description:

BDRK-S-1 (45-55')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. G.112

Date: 6/26/02

Description:

BDRK-S-1 (55-65')





Photo No. G.113 **Date:** 6/26/02

Description:

BDRK-S-1 (65-75')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. G.114

Date: 6/26/02

Description:

BDRK-S-1 (75-80')







Photo No. Date: 6/26/02 G.115

Description:

BDRK-S-1 (80-95')







PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No. Sauget, Illinois

21560888

Photo No. Date: G.118

6/26/02

Description:

BDRK-S-1 (105-115')





Photo No. G.119

Date: 6/26/02

Description:

BDRK-S-1 (115-135')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 6/26/02

Description:

BDRK-S-1 (127-132')




Photo No. Date: 6/26/02

Description:

BDRK-S-1 (132-135')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Date:

6/26/02

Site Location:

Sauget, Illinois

Project No.

21560888

G.122

Photo No.


Description:BDRK-S-1-Drilling fro 135-145'



Photo No. Date: 6/26/02 G.123

Description:

BDRK-S-1 (135-145')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. G.124 Date: 6/26/02

Description:

BDRK-S-1 (142-145')



Photo No. G.125 **Date:** 6/26/02

Description:

BDRK-S-1 (145-155")



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. G.126

Date: 6/26/02

Description:

BDRK-S-1 (155-158')



Photo No. G.127

Date: 6/26/02

Description: BDRK-S-1 (158-165')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **G.128**

Date: 6/26/02

Description: BDRK-S-1 Well Installation

Direction Photo

Taken: West



Photo No. G.129

Date: 6/26/02

Description:

BDRK-S-1 Well Installation

Direction Photo

Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Date:

6/26/02

Site Location:

Sauget, Illinois

Project No.

21560888

G.130

Photo No.

Description: BDRK-S-1-Well Installation




Photo No. G.131

Date: 6/26/02

Description: BDRK-S-1-Well Installation



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location: Sauget, Illinois

Project No.

21560888

Photo No. G.132

Date: 6/26/02

Description: BDRK-S-1 Crack in Surface Soil



Photo No. G.133

Date: 6/26/02

Description: BDRK-S-1 Crack in Surface Soil



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No. 21560888

Photo No.

Date: 6/26/02

G.134

Description: BDRK-S-1 Crack in Surface Soil



Photo No. **G.135**

Date: 6/26/02

Description: BDRK-S-1 Crack in

Surface Soil



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. **G.136**

Date: 6/26/02

Description:BDRK-S-1 Existing crack in foundation wall of building




Photo No. **G.137**

Date: 6/26/02

Description:

BDRK-S-1 Existing crack in foundation wall of building



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. G.138

Date: 6/26/02

Description:

BDRK-S-1 Existing crack in foundation wall of building




Photo No. G.139

Date: 6/26/02

Description: BDRK-S-1 After

Direction Photo Taken: South



URS PHOTOGRAPHIC LOG Project No. **Client Name:** Site Location: Sauget Area 2 Group Sauget, Illinois 21560888 Photo No. Date: G.140 6/26/02 Description: BDRK-S-1 After **Direction Photo** Taken: North

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

Photo No.

H.1

Date: 7/11/02

Description: BDRK-P-1

21560888

Direction Photo

Taken:

South



Photo No. H.2

Date: 6/19/02

Description: BDRK-R-1

Direction Photo Taken: North



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/17/02

Description:

Piez-1

Direction Photo

Taken: South



Photo No.

Date: 7/17/02

Description:

Piez-1

Direction Photo Taken:

South



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. 1.3

Date: 7/17/02

Description:

Piez-1

Direction Photo Taken:

South




Photo No. 1.4

Date: 7/17/02

Description:

Piez-1

Direction Photo Taken: North



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

21560888

Photo No. 1.5

Date:

7/17/02

Description: Piez-1 (0-5')




Photo No.

Date: 7/17/02 1.6

Description:

Piez-1 (5-15')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. 1.7

Date: 7/17/02

Description:

Piez-1 (7-17')





Photo No. 1.8

Date: 7/17/02

Description: Piez-1 (7-17')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/17/02

Description:

Piez-1 (15-20')




Photo No.

Date: 7/17/02

Description:

Piez-1 (25-35')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Photo No.

Date: 7/17/02 Sauget, Illinois

21560888

1.11 Description:


Piez-1 (25-35')



Photo No. 1.12

Date: 7/17/02

Description: Piez-1 (35-55')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. 1.13

Date: 7/17/02

Description:


Piez-1 (55-75')



Photo No. 1.14

Date: 7/17/02

Description: Piez-1 (95-115')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois


Project No.

21560888

Photo No. 1.15

Date: 7/17/02

Description: Piez-1 (120-125')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 7/12/02

Description:

Piez-2 (27-37')





Photo No.

Date: 7/12/02

Description:

Piez-2 (27-37')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 7/12/02

Description:

Piez-2 (37-57')





Photo No.

Date: 7/12/02

Description:

Piez-2 (37-57')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/12/02

Description:

Piez-2 (57-73')






Photo No.

Date: 7/12/02

Description:

Piez-2 (107-117')





PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. 1.23

Date:

7/22/02

Description:

Piez-3

Direction Photo

Taken: East



Photo No. 1.24


Date: 7/22/02

Description:

Piez-3

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. 1.25

Date: 7/22/02

Description:

Piez-3

Direction Photo

Taken: East



Photo No. 1.26

Date: 7/22/02

Description:

Piez-3

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. 1.27

Date: 7/22/02

Description:

Piez-3

Direction Photo

Taken:

Northeast




Photo No. 1.28

Date: 7/22/02

Description:

Piez-3

Direction Photo

Taken: Northeast



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illniois

Project No.

21560888

Photo No.

Date: 7/22/02

Description:

Piez-3

Direction Photo Taken:

West



Photo No.


Date: 7/22/02

Description:

Piez-3

Direction Photo

Taken: West



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. 1.31

Date: 7/22/02

Description:

Piez-3




Photo No.

1.32

Date: 7/22/02

Description: Piez-3 (0-5')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. 1.33

Date: 7/22/02


Description: Piez-3 (5-15')



Photo No. 1.34

Date: 7/22/02

Description: Piez-3 (15-25')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 1.35

7/22/02

Description:

Piez-3 (15-25')





Photo No. 1.36

Date: 7/22/02

Description: Piez-3 (25-30')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/22/02

Description: Piez-3 (35-55')





Photo No.

Date: 7/22/02

Description: Piez-3 (55-65')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Sauget, Illinois

21560888

Photo No. 1.39

Date: 7/22/02

Description:

Piez-3 (70-85')




Photo No. 1.40

Date: 7/22/02

Description: Piez-3 (70-85')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. Date: 1.41 7/22/02

Description: Piez-3 (85-105')




Photo No. 1.42

Date: 7/22/02

Description:

Piez-3 (105-110')



PHOTOGRAPHIC LOG

Client Name:

Site Location: Sauget Area 2 Group

Sauget, Illinois

Project No.

Photo No. 1.43

Date: 7/23/02 21560888

Description:


Piez-4 (0-7')



Photo No. Date:

1.44 7/23/02

Description: Piez-4 (7-17')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. 1.45

Date: 7/23/02

Description:

Piez-4 (27-37')





Photo No.

Date: 1.46 7/23/02

Description:

Piez-4 (37-47')







Photo No. I.48

Date: 7/23/02

Description: Piez-4 (87-97')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location: Sauget, Illinois

Project No.

Photo No.

1.49

Date: 7/23/02 21560888

Description:

Piez-4 (97-107')



Photo No. Date: 1.50 7/23/02

Description:

Piez-4 (107-113')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Date:

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

1.51 7/23/02

Description:

Piez-4 (113-123')





Photo No.

1.52

Date: 7/23/02

Description:

Piez-4 (128-132')



Client Name: Sauget Area 2 Group Site Location: Sauget, Illinois Photo No. I.53 Description: Piez-4 (128-132') Photographic Log Project No. 21560888

Photo No. Date: 7/23/02

Description: Piez-4-Broken riser pipe



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. 1.55

Date: 7/23/02

Description:

Piez-4-Broken riser

pìpe




Photo No. 1.56


Date: 12/11/02

Direction Photo

Taken: West

Description:

Berm in front of Piez-4



PHOTOGRAPHIC LOG

Client Name:Site Location:Project No.Sauget Area 2 GroupSauget, Illinois21560888

Description: Piez-5 (0-6')





Photo No. | Date: 7/29/02

Description: Piez-5 (0-6')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. 1.59

Date: 7/29/02

Description:

Piez-5 (6-16')





Photo No. 1.60

Date: 7/29/02

Description: Piez-5 (6-16')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. 1.61

Date: 7/29/02

Description: Piez-5 (16-26')





Photo No. 1.62

Date: 7/29/02

Description:

Piez-5 (31-41')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Date:

Site Location:

Project No.

Sauget, Illinois

21560888

1.63 Description:

Photo No.

Piez-5 (31-41')





Photo No. 1.64

Date: 7/29/02

Description: Piez-5 (41-56')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. 1.65

Date: 7/29/02

Description:


Piez-5 (56-75')



Photo No. 1.66

Date: 7/29/02

Description: Piez-5 (56-75')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 7/29/02

Description:

Piez-5 (80-96')





Photo No. I.68 **Date:** 7/29/02

Description:

Piez-5 (96-113')



PHOTOGRAPHIC LOG

Project No.

Client Name:

Sauget Area 2 Group

Site Location:

Photo No. 1.69

Date: 7/30/02

Description: Piez-6 (0-6')





Photo No. 1.70

Date: 7/30/02

Description: Piez-6 (6-16')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/30/02

Description:

Piez-6 (16-26')



Photo No.

Date: 7/30/02

Description: Piez-6 (26-46')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. 1.73

Date: 7/30/02

Description: Piez-6 (26-46')




Photo No. 1.74

Date: 7/30/02

Description: Piez-6 (46-66')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Sauget, Illinois

Photo No. 1.75

Date: 7/30/02

21560888

Description: Piez-6 (66-86')





Photo No. 1.76

Date: 7/30/02

Description: Piez-6 (91-101')





PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Photo No.

Date: 8/05/02

Sauget, Illinois

21560888

Description:

Piez-7 (0-5')



Photo No.

No. Date: 8/05/02

Description: Piez-7 (5-15')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 8/05/02

Description:

Piez-7 (5-15')





Photo No.

Date: 8/05/02

Description:

Piez-7 (25-45')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location: Sauget, Illinois

Project No.

21560888

Photo No. 1.83

Date: 8/05/02

Description: Piez-7 (25-45')



Photo No. 1.84

Date: 8/05/02

Description: Piez-7 (45-65')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. | Date: 8/05/02

Description: Piez-7 (70-85')



Photo No.

Date: 8/05/02

Description: Piez-7 (70-85')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Date:

8/05/02

Site Location:

Project No.

Sauget, Illinois

21560888

1.87

Photo No.

Description: Piez-7 (85-105')



Photo No.

Date: 8/05/02 1.88

Description: Piez-7 (115-116')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. 1.89

Date: 7/29/02

Description: Piez-8 (0-5')





Photo No. 1.90

Date: 7/29/02

Description: Piez-8 (5-15')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Sauget, Illinois

21560888

1.91

Photo No.

Date: 7/29/02

Description:

Piez-8 (15-20')





Photo No. 1.92

Date: 7/29/02

Description: Piez-8 (30-45')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. 1.93

Date: 7/29/02

Description: Piez-8 (45-65')




Photo No. 1.94

Date: 7/29/02

Description: Piez-8 (75-95')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. 1.95

Date: 7/29/02

Description: Piez-8 (75-95')





Photo No. 1.96

Date: 7/29/02

Description: Piez-8 (105-110')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/29/02

Description:

Piez-8 (110-115')





Photo No.

Date: 7/29/02

Description: Piez-8-After

Direction Photo Taken: North



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/31/02

Description:

Piez-9

Direction Photo

Taken: South



Photo No.

Date: 7/31/02

Description:

Piez-9

Direction Photo Taken: South



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No. 1.101

Date: 7/31/02

Description: Piez-9 (0-5')



Photo No. 1.102

Date: 7/31/02

Description: Piez-9 (5-15')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

1.103

Date: 7/31/02

Description: Piez-9 (15-20')





Photo No. 1.104

Date: 7/31/02

Description: Piez-9 (25-35')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

21560888

Photo No. 1.105

Date: 7/31/02


Description: Piez-9 (25-35')



Photo No. 1.106

Date: 7/31/02

Description: Piez-9 (25-35')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 7/31/02

Description: Piez-9 (35-55')





Photo No.

Date: 7/31/02

Description: Piez-9 (55-60')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No. 21560888

Sauget Area 2 Group Photo No.

1.109

Date: 7/31/02

Description: Piez-9 (75-85')



Photo No. 1.110

Date: 7/31/02

Description: Piez-9 (85-100')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illniois

21560888

Photo No.

Date: 7/31/02

Description:

Piez-9 (105-108')





Photo No.

Date: 7/31/02

Direction Photo Taken:

North

Description: Piez-9-After



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illniois

21560888

Photo No.

Date: 7/31/02

Direction Photo

Taken: South

Description:

Piez-9-After



Photo No.

Date: 7/31/02

Direction Photo

Taken:

East

Description:

Piez-9-After



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group


Sauget, Illinois

21560888

Photo No.

Date: 7/31/02

Description: Piez-9-After



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: **J.1**

8/14/02

Description: OS-1 (0-4)





Photo No. **J.2**

Date: 8/14/02

Description: OS-1 (4-6')



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 8/14/02

Description: OS-2 (0-4')





Photo No.

Date: 8/14/02

Description: OS-2 (4-6')



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

Photo No. **K.1**

Date: 8/17/02

Description:

General Site Area

21560888

Direction Photo

Taken: East



Photo No. **K.2**

Date: 8/17/02

Description:

General Site Area

Direction Photo Taken: North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **K.3**

Date: 8/17/02

Description:

General Site Area

Direction Photo Taken:

South



Photo No. **K.4**

Date: 8/17/02

Description:

General Site Area

Direction Photo Taken: West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **K.5**

Date: 8/17/02

Description:

Met Station

Direction Photo Taken:

South





Photo No. **K.6**

Date: 8/17/02


Description: Met Station

Direction Photo

Taken: North



URS				OGRAPHIC LOG	
Client Name	e:	Site Location:		Project No.	
Sauget Area	a 2 Group	Sauget, Illinois		21560888	
Photo No. K.7	Date: 8/17/02				
Description Air-P-1	:				
Direction Pl Taken: North	hoto				
				er († 1	
		*.			




URS PHOTOGRAPHIC LOG Project No. **Client Name:** Site Location: 21560888 Sauget Area 2 Group Sauget, Illinois Photo No. Date: **K.9** 8/17/02 Description: Air-P-1 samplers **Direction Photo** Taken: North

Photo No. K.10 Date: 8/17/02

Description:

Air-P-2

Direction Photo Taken: East



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No. 21560888

Photo No.

Date: 8/17/02

Description:

Air-P-2

Direction Photo

Taken: North



Photo No. K.12 Date: 8/17/02

Description:

Air-P-2

Direction Photo Taken:
South



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Project No.

Sauget, Illinois

21560888

Photo No. K.13

Date:

8/17/02

Description:

Air-P-2

Direction Photo

Taken: West



Photo No. K.14


Date: 8/17/02

Description:

Air-P-2 samplers

Direction Photo Taken:

East



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Photo No. Date: 8/17/02

Sauget, Illinois

21560888

K.15
Description:

Air-P-3

Direction Photo

Taken: East



Photo No. K.16 Date: 8/17/02

Description:

Air-P-3

Direction Photo Taken: North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. K.17

Date: 8/17/02

Description:

Air-P-3

Direction Photo

Taken: South





Photo No. K.18

Date: 8/17/02

Description:

Air-P-3

Direction Photo Taken: West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. K.19

Date: 8/17/02

Description:

East

Air-P-3 samplers







Photo No. K.20 **Date:** 8/17/02

Description:


Air-P-4

Direction Photo Taken:

East



URS PHOTOGRAPHIC L			TOGRAPHIC LOG
Client Name):	Site Location:	Project No.
Sauget Area	2 Group	Sauget, Illinois	21560888
Photo No. K.21 Description:	Date: 8/17/02		
Air-P-4			
Direction Ph Taken: North	oto	##W	



URS			PHOTOGRAPHIC LOG	
Client Name	e:	Site Location:	Project No.	
Sauget Area	2 Group	Sauget, Illinois	21560888	
Photo No. K.23	Date: 8/17/02		-	
Description Air-P-4				
Direction Ph Taken: West	noto		,°E	
),	

Photo No. K.24	Date: 8/17/02			·
Description:				
Air-P-4 samp	lers			
	····			
Direction Ph Taken:	oto			
West				
			1	•
				†
		1, %	. •	
		<u> </u>		

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **K.25**

Date: 8/17/02

Description:

Air-Q-3

Direction Photo

Taken: East



Photo No. **K.26**

Date: 8/17/02

Description:

Air-Q-3

Direction Photo Taken: North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. K.27

Date: 8/17/02

Description:

Air-Q-3

Direction Photo Taken:

South



Photo No. K.28

Date: 8/17/02

Description:

Air-Q-3

Direction Photo Taken: West



PHOTOGRAPHIC LOG

Client Name:Site Location:Project No.Sauget Area 2 GroupSauget, Illinois21560888

Description: Air-Q-3 samplers

Direction Photo Taken:East



Photo No. K.30 8/17/02

Description:
Air-Q-5

Direction Photo Taken:
Northwest

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date:

K.31 8/17/02

Air-Q-

Description:

Direction Photo Taken:

East 7




Photo No. K.32

Date: 8/17/02

Description:

Air-Q-7

Direction Photo

Taken: North



PHOTOGRAPHIC LOG

Client Name:Site Location:Project No.Sauget Area 2 GroupSauget, Illinois21560888

Photo No. Date: 8/17/02


Description: Air-Q-7

Direction Photo Taken: South




Description: Air-Q-7

Direction Photo Taken: West



URS **PHOTOGRAPHIC LOG** Client Name: Project No. Site Location: Sauget Area 2 Group Sauget, Illinois 21560888 Photo No. Date: K.35 8/17/02 **Description:**Air-Q-7 samplers **Direction Photo** Taken: North

URS PHOTOGRAPHIC LOG Project No. **Client Name:** Site Location: 21560888 Sauget Area 2 Group Sauget, Illinois Photo No. Date: K.36 8/17/02 Description: Air-R-1 **Direction Photo** Taken: East




URS PHOTOGRAPHIC LOG Project No. Client Name: Site Location: 21560888 Sauget Area 2 Group Sauget, Illinois Photo No. Date: **K.38** 8/17/02 Description: Air-R-1 **Direction Photo** Taken: South

Photo No. K.39

Description:
Air-R-1

Direction Photo Taken: West




URS **PHOTOGRAPHIC LOG** Project No. **Client Name:** Site Location: 21560888 Sauget Area 2 Group Sauget, Illinois Photo No. Date: K.40 8/17/02 Description: Air-R-1 samplers **Direction Photo** Taken: East

K.41	8/17/02	
Description Air-R-2):	
Direction P Taken: North	hoto	
		The second secon

Photo No. Date:


URS			PHOTOGRAPHIC LOG	
Client Name	e:	Site Location:	Project No.	
Sauget Area	2 Group	Sauget, Illiniois	21560888	
Photo No. K.42	Date: 8/17/02		i i i i i i i i i i i i i i i i i i i	
Description Air-R-2	:			
Direction Pl Taken: South	hoto	· · · · · · · · · · · · · · · · · · ·		



URS PHOTOGRAPHIC LOC				
Client Name: Site Location: Project No.			Project No.	
Sauget Area 2 Group		Sauget, Illinois	21560888	
Photo No. K.44	Date: 8/17/02			
Description Air-R-3				
Direction Pl Taken: East	hoto			



URS				
Client Name) :	Site Location:	Project No.	
Sauget Area	2 Group	Sauget, Illinois	21560888	
Photo No. K.46	Date: 8/17/02	g (Mar-		
Description Air-R-3		,		
Direction Ph Taken: South	noto	- -		
		- :		



URS		PHOTOGRAPHIC LOG		
Client Name	9:	Site Location:	Project No.	
Sauget Area	2 Group	Sauget, Illinois	21560888	
Photo No. K.48	Date: 8/17/02			
Description Air-R-3 sam	: plers			
Direction PI Taken: East	hoto			



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location: Sauget, Illinois Project No.

Photo No. K.50

Date: 8/17/02

21560888

Description:

Air-R-4

Direction Photo

Taken: East




Photo No. K.51

Date: 8/17/02

Description:

Air-R-4

Direction Photo Taken: North



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 8/17/02 K.52

Description:

Air-R-4

Direction Photo

Taken: South



Photo No. K.53

Date: 8/17/02

Description:

Air-R-4

Direction Photo Taken:

West



URS PHOTOGRAPHIC LOG **Client Name:** Site Location: Project No. Sauget Area 2 Group 21560888 Sauget, Illinois Photo No. Date: K.54 8/17/02 Description: Air-R-4 samplers **Direction Photo** Taken: East

URS PHOTOGRAPHIC LOG Client Name: Site Location: Project No.

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No.

Date: 9/2002

Description: Seep-P




Photo No.

Date: 9/2002

Description: Seep-P



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 9/2002

Description: Seep-P



Photo No.


Date: 9/2002

Description:

Seep-P

Direction Photo Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **L.5**

Date:

9/2002

Description: Seep-P



Photo No. **L.6**

Date: 9/2002

Description:

Seep-P



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **L.7**

Date: 9/2002

Description:

Seep-P



Photo No. **L.8**

Date: 9/2002

Description:

Seep-P



URS Client Name: Sauget Area 2 Group Site Location: Sauget, Illinois Project No. 21560888

Description: Seep-P



Photo No. Date: 9/2002

Description: Seep-P



PHOTOGRAPHIC LOG

Client Name:Site Location:Project No.Sauget Area 2 GroupSauget, Ilinois21560888



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. L.12

Date: 8/06/02

Description:

Site-Q




Photo No. L.13

Date: 8/06/02



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. L.14

Date: 8/06/02

Description: Seep-Q-1



Photo No. L.15

Date: 8/06/02



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. L.16

Date: 8/06/02

Description: Site-Q-1



Photo No. L.17

Date: 8/06/02



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. L.18

Date:

8/06/02

Description: Seep-Q-1




Photo No. L.19

Date: 8/06/02

Description: Seep-Q-2

Direction Photo Taken: South



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **L.20**

Date:

8/06/02

Description: Site-Q-2





Photo No. L.21

Date: 8/06/02



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. L.22

Date:


8/06/02

Description: Seep-Q-2



Photo No. L.23

Date: 8/06/02



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. L.24

Date: 8/5/02


Description: Seep-R



Photo No. L.25

Date: 8/5/02

Description: Seep-R-1 Concrete



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 8/5/02

Description:

Seep in R (unable to sample)




Photo No. L.27

Date: 8/5/02

Description:

Seep in R (unable to sample)



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. L.28

Date: 8/05/02

Description:

Seep in R (unable to sample)




Photo No. L.29

Date: 8/5/02

Description: Seep in R (unable to sample)



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. L.30

Date: 8/05/02

Description: Seep in R (unable to sample)



Photo No. L.31

Date: 8/05/02



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 8/05/02

Description: Seep-R-2




Photo No.

Date: 8/05/02



PHOTOGRAPHIC LOG

Client Name:

Sauget Area 2 Group

Site Location:

Sauget, Illinois

Project No.

21560888

Photo No. L.34

Date: 8/05/02

Description: Seep-R-2



Photo No. L.35

Date: 8/05/02



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No.

21560888

Photo No.

Date: 8/05/02

Description: Seep-R-2



Photo No. L.37 Date: 8/05/02



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Sauget Area 2 Group

Sauget, Illinois

Project No. 21560888

Photo No.

Date: 8/05/03



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. M.1

Date:

8/28/02

Description: Slug Tests





Photo No.

Date: 8/28/02 **M.2**

Description: SlugTests



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. **N.1**

Date:

8/12/02

Description:

Site-P-Dumped drum and metal

Direction Photo Taken:

East



Photo No.

Date: **N.2** 8/12/02

Description:

Site-P-Dumped drum and metal

Direction Photo Taken: South



Client Name: Sauget Area 2 Group Photo No. N.3 B/12/02 Description: Site P-Dumped drum and metal

PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No. 0.1

Date:

12/11/02

Description:

Large Pond

Direction Photo Taken:

Northwest



Photo No. 0.2

Date: 12/11/02

Description:

Large Pond close-up

Direction Photo

Taken: Northwest



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

21560888

Photo No.

Date: 12/11/02

Description:

Large Pond overview

Direction Photo

Taken:

South




Photo No.

0.4

Date: 12/11/02

Description: Small Pond (north)

Direction Photo

Taken:

West



PHOTOGRAPHIC LOG

Client Name:

Site Location:

Project No.

Sauget Area 2 Group

Sauget, Illinois

Photo No. 0.5

Date: 12/11/02

Description:

Small Pond (south)

21560888

Direction Photo

Taken:

Northwest




Photo No.

Date: 12/11/02 0.6

Description:

Small Pond overview

Direction Photo Taken: Southeast

